

Fox Electronics Headquarters
 5570 Enterprise Parkway
 Fort Myers, FL 33905 USA
 Tel: 888-GET-2-FOX
 Outside US: +1.239.693.0099
 Fax: +1.239.693.1554

Fox Electronics EMEA
 14 Banks Road
 Biggleswade, Bedfordshire
 SG18 0DY, United Kingdom
 Tel/Fax: +44.1767.312632

Fox Electronics Asia
 4/F Gold & Silver Commercial Bldg.
 12-18 Mercer St.
 Central, Hong Kong
 Tel: +852.2854.4285
 Fax: +852.2854.4282

Fox Electronics Japan
 3-28-6-1A Yoyogi
 Shibuya-ku, Tokyo 151
 Japan
 Tel: +81.3.3374.2079
 Fax: +81.3.3377.5221

Product Change Notification

PCN Publish Date: 02/07/2007

PCN#: 261

Change Title: Product End of Life (EOL)

Products Affected: RFXO Series – All Versions.
 See table below for all affected models/part numbers and recommended substitutions.

Description of Change to the Customer: In an effort to streamline our oscillator line, Fox Electronics will be discontinuing all versions of the RFXO Series.

Recommended substitutions for the 3.3V Oscillator (RFX300) and the 3.3V VCXO (RFV300) is the new XpressO series. http://www.foxonline.com/xpresso_main.htm
 There currently is no recommended substitution for the 2.5V Oscillator (RFX250) and 2.5V VCXO (RFV250)²

Affected Model / Part Numbers and Recommended Substitutions.

Fox Model Number	Fox Part Number	Recommended Substitution Model Number	Recommended Substitution Part Number	Datasheet
RFX300	913-frequency-xxxxx	FXO-PC738 (± 20 PPM, $-20\sim+70^{\circ}\text{C}$) FXO-PC736R (± 25 PPM, $-40\sim+85^{\circ}\text{C}$)	774-frequency-xxxxx ¹	FXO_PC73.pdf
RFV300	905-frequency-xxxxx	FVXO-PC73B (± 50 PPM APR, $-20\sim+70^{\circ}\text{C}$) FVXO-PC73BR (± 50 PPM APR, $-40\sim+85^{\circ}\text{C}$)	796-frequency-xxxxx ¹	FVXO_PC73.pdf
RFX250	680-frequency-xxxxx	No recommended substitution ²		
RFV250	681-frequency-xxxxx	No recommended substitution ²		

¹(xxxxx = random number.

For more information on Fox part numbers, see <http://foxonline.com/onefamilytype.asp> on the Fox website.)

(Note: We recommend a sample be evaluated in all applications before making a substitution.)

Schedule of Change: EOL is effective immediately.
²All versions will be supported until existing inventory is depleted.

Customer Impact and Response: We expect this product discontinuance will have minimal impact on our customers. If you have any questions or need assistance in determining a suitable substitution, please email Fox Technical Support at www.foxonline.com/email.htm or call 239-693-0099.