

Fox Electronics Headquarters
5570 Enterprise Parkway
Fort Myers, FL 33905 USA
Tel: 888-GET-2-FOX
Outside US: +1.239.693.0099
Fax: +1.239.693.1554

Fox Electronics EMEA
Tel/Fax: +44.1767.312632

Fox Electronics Asia
4/F Gold & Silver Commercial Bldg.
12-18 Mercer St.
Central, Hong Kong
Tel: +852.2854.4285
Fax: +852.2854.4282

Fox Electronics Japan
3-28-6-1A Yoyogi
Shibuya-ku, Tokyo 151
Japan
Tel: +81.3.3374.2079
Fax: +81.3.3377.5221

Product Change Notification

PCN Publish Date: 09/03/2010

PCN#: 361

Change Title: Pin Connection Recommendation

Products Affected:

Model Number	Part Number
FSRLF	414LF-0.032768-xxxxx
FSRLF	FSRLF327
FSXLF	501LF-0.032768-xxxxx
FSXLF	FSXLF327

Description of Change to the Customer: A statement has been added to these product's datasheets that the non-crystal pins (pins #2 and #3) should be electrically unconnected (open).

Reason for Change: Connecting these pins to the circuit can result in frequency shift.

Schedule of Change: Change is effective immediately.

Customer Impact and Response: We sincerely hope this change will have minimal impact on our customers. If you have any questions, please contact Fox Technical Support at www.foxonline.com/email.htm or call 239-693-0099.